EMCBC-OLS-0001-10



## **Department of Energy**

Environmental Management Consolidated Business Center 250 East 5<sup>th</sup> Street, Suite 500 Cincinnati, Ohio 45202 (513) 246-0500

January 4, 2010

Mr. Andrew Taylor Case Developer, Mail Stop SFD-7-5 U.S. Environmental Protection Agency, Region IX 75 Hawthorne Street San Francisco, CA 94105

RE: Request for Information Pursuant to CERCLA Section 104(e); Santa Susana Field Laboratory, Ventura County, California Dated June 24, 2009

Dear Mr. Taylor:

Enclosed is U.S. Department of Energy's (DOE) December 31, 2009, supplemental response to the Region IX U.S. Environmental Protection Agency's June 24, 2009, Request for Information letter addressed to Melanie Pearson (now Hurley). An inventory of the documents on the disc is included, indentifying them by the identification number, title and date created.

DOE continues with its review of documents in its possession for responsive documents. We anticipate providing more responsive documents on January 29, 2010. Please let me know if you have any questions with respect to the documents provided with this supplemental response.

General Attorney

Office of Legal Services

cc electronically:

John Lyons, EPA
Rick Brausch, California Department of Toxic Substances Control
Tania Smith, DOE-HQ, EM 3.3
Richard Schassburger, DOE-OAK
William Backous, DOE-ETEC
Mell Roy, EMCBC

## Inventory of 12-31-09 DOE Supplemental Response to EPA 104(e) Letter

		Date		Responds to	
DIIN	Title	Created	Author	question #	Synopsis
ET001667	Environmental and Radioactive Effluent Monitoring Annual Report 1973	1/1/1973	J. D. Moore	13, 10	31 pgs. Report of site emissions and local area samples, near both Canoga Park and SSFL sites. Concludes area radioactivity is due to natural environment, and not from Atomic Intl activities.
ET001668	Atomics International	1/1/1976	J. D. Moore	13, 10	46 pg. Atomics Intl doc #AI-77-14. Environmental and Radioactive Effluent Monitoring Annual Report 1976. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001669	Energy Ststems Group Environmental Monitoring and Facility Effluent Annual Report	1/1/1978	J. D. Moore	13, 10	60 pg. Rockwell doc #ESG-79-7. Effluent Monitoring Annual Report 1978. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001670	Energy Systems Group Environmental Monitoring and Facility Effuent Annual Report 1973	1/1/1979	Rockwell International / J. D. Moore	13,10	26 pg. Rockwell doc #ESG-80-7. Effluent Monitoring Annual Report 1979. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001671	Energy System Group Environmental Monitoring and Facility Effluent Annual Report	1/1/198	J. D. Moore	13, 10	58 pg. Rockwell doc #ESG-81-17. Effluent Monitoring Annual Report 1980. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001672	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1981	1/1/1981	J. D. Moore	13, 10	66 pg. Rockwell doc #ESG-82-21. Effluent Monitoring Annual Report 1981. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001673	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1982	1/1/1982		13, 10	68 pg. Rockwell doc #ESG-83-17. Effluent Monitoring Annual Report 1982. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001674	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1983	1/1/1983	J. D. Moore	13, 10	74 pg. Rockwell doc #ESG-84-9. Effluent Monitoring Annual Report 1983. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001675	Rocketdyne Division Environmental Monitoring at Facility Effluent Annual Report DeSoto and SSFt 1984		Bldg 21 and 22	13, 10	86 pg. Rockwell doc #RI/RD85-123. Effluent Monitoring Annual Report 1984. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001676	Rocketdyne Division Environmental Monitoring and and Facility Effluent Annual report Desoto an SSFL Sites 1985	1/1/1985 d	Rockweli Internationa/ J.D. Moore	13, 10	82 pg. Rockwell doc #RI/RD86-140. Effluent Monitoring Annual Report 1985. Report of site emissions and local area samples, near both DeSoto and SSFL sites.

,

DIIN	Date Title Created	Author	Responds to question #	Synopsis
ET001677	Rocketdyne Division Environmental Monitoring and 1/1/1986 Facility Effluent Annual Report DeSoto and SSFL 1986	J. D. Moore	13, 10	88 pg. Rockwell doc #RI/RD87-133. Effluent Monitoring Annual Report 1986. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001678	Rocketdyne Division Environmental Monitoring and 1/1/1987 Facility Effluent Annual Report DeSoto and SSFL 1987	J. D. Moore	13, 10	82 pg. Rockwell doc #RI/RD88-144. Effluent Monitoring Annual Report 1987. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001679	Rocketdyne Division Environmental Monitoring and 1/1/1988 Facility Effluent Annual Report DeSoto and SSFL 1988	J. D. Moore	13, 10	92 pg. Rockwell doc #RI/RD89-139. Effluent Monitoring Annual Report 1988. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001680	Rocketdyne Division Environmental Monitoring and 1/1/1989 Facility Effluent Annual Report DeSoto and SSFL 1989		13. 10	148 pg. Rockwell doc #RI/RD90-132. Monitoring & Effluent Annual Report 1989. Report of site emissions and local area samples, near both DeSoto and SSFL sites. Incl Self-Assmt of JAN- MAY90 environmental (non-rad) ops. Incl report of non-rad emissions.
ET001681	Rocketdyne Division Environmental Annual Report 1/1/1990 SSFL DeSoto, and Canoga Sites 1990	J. D. Moore	13, 10	112 pg. Rockwell doc #RI/RD91-136. Monitoring & Effluent Annual Report 1990. Report of site emissions and local area samples, near both DeSoto and SSFL sites. Incl report of non-rad emissions. Incl self-assmt for JAN- MAR91.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001682	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1991	1/1/1991		13, 10	94 pg. Rockwell doc #RI/RD92-138. ASER 1991. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001683	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1992	1/1/1992	Radiation Protection and Health Physics Services	13, 10	118 pg. Rockwell doc #RI/RD93-125. ASER 1992, Rev A (DEC93). Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001684	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1993	1/1/1993	Radiation Protection and Health Physics Service and Environmental Protecti	13, 10 ion	118 pg. Rockwell doc #RI/RD94-126. ASER 1993. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001685	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1994	1/1/1994	Radiation Protection and Health Physics Services and Environmental Protection	13, 10	118 pg. Rockwell doc #Rt/RD95-153. ASER 1994. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001686	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1992	1/1/1985	Staff of Environmental Remediation	13, 10	116 pg. Rockwell doc #RI/RD96-140. ASER 1995. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.

## Inventory of 12-31-09 DOE Supplemental Response to EPA 104(e) Letter

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001667	Environmental and Radioactive Effluent Monitoring Annual Report 1973	j 1/1/1973	J. D. Moore	13, 10	31 pgs. Report of site emissions and local area samples, near both Canoga Park and SSFL sites. Concludes area radioactivity is due to natural environment, and not from Atomic Intl activities.
ET001668	Atomics International	1/1/1976	J. D. Moore	13, 10	46 pg. Atomics Intl doc #AI-77-14. Environmental and Radioactive Effluent Monitoring Annual Report 1976. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001669	Energy Ststems Group Environmental Monitoring and Facility Effluent Annual Report	1/1/1978	J. D. Moore	13, 10	60 pg. Rockwell doc #ESG-79-7. Effluent Monitoring Annual Report 1978. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001670	Energy Systems Group Environmental Monitoring and Facility Effuent Annual Report 1973	1/1/1979	Rockwell International and J. D. Moore	/ 13,10	26 pg. Rockwell doc #ESG-80-7. Effluent Monitoring Annual Report 1979. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001671	Energy System Group Environmental Monitoring and Facility Effluent Annual Report	1/1/198	J. D. Moore	13, 10	58 pg. Rockwell doc #ESG-81-17. Effluent Monitoring Annual Report 1980. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001672	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1981	1/1/1981	J. D. Moore	13, 10	66 pg. Rockwell doc #ESG-82-21. Effluent Monitoring Annual Report 1981. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001673	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1982	1/1/1982		13, 10	68 pg. Rockwell doc #ESG-83-17. Effluent Monitoring Annual Report 1982. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001674	Energy Systems Group Environmental Monitoring and Facility Effluent Annual Report 1983	1/1/1983	J. D. Moore	13, 10	74 pg. Rockwell doc #ESG-84-9. Effluent Monitoring Annual Report 1983. Report of site emissions and local area samples, near both Canoga Park and SSFL sites.
ET001675	Rocketdyne Division Environmental Monitoring an Facility Effluent Annual Report DeSoto and SSFL 1984		Bldg 21 and 22	13, 10	86 pg. Rockwell doc #RI/RD85-123. Effluent Monitoring Annual Report 1984. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001676	Rocketdyne Division Environmental Monitoring and and Facility Effluent Annual report Desoto and SSFL Sites 1985	1/1/1985 d	Rockwell Internationa/ J.D. Moore	13, 10	82 pg. Rockwell doc #RI/RD86-140. Effluent Monitoring Annual Report 1985. Report of site emissions and local area samples, near both DeSoto and SSFL sites.

•

DIIN	Title Date Created	Author	Responds to question #	Synopsis
ET001677	Rocketdyne Division Environmental Monitoring and 1/1/1986 Facility Effluent Annual Report DeSoto and SSFL 1986	J. D. Moore	13, 10	88 pg. Rockwell doc #RI/RD87-133. Effluent Monitoring Annual Report 1986. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001678	Rocketdyne Division Environmental Monitoring and 1/1/1987 Facility Effluent Annual Report DeSoto and SSFL 1987	J. D. Moore	13, 10	82 pg. Rockwell doc #RI/RD88-144. Effluent Monitoring Annual Report 1987. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001679	Rocketdyne Division Environmental Monitoring and 1/1/1988 Facility Effluent Annual Report DeSoto and SSFL 1988	J. D. Moore	13, 10	92 pg. Rockwell doc #RI/RD89-139. Effluent Monitoring Annual Report 1988. Report of site emissions and local area samples, near both DeSoto and SSFL sites.
ET001680	Rocketdyne Division Environmental Monitoring and 1/1/1989 Facility Effluent Annual Report DeSoto and SSFL 1989		13, 10	148 pg. Rockwell doc #RI/RD90-132. Monitoring & Effluent Annual Report 1989. Report of site emissions and local area samples, near both DeSoto and SSFL sites. Incl Self-Assmt of JAN- MAY90 environmental (non-rad) ops. Incl report of non-rad emissions.
ET001681	Rocketdyne Division Environmental Annual Report 1/1/1990 SSFL DeSoto, and Canoga Sites 1990	J. D. Moore	13, 10	112 pg. Rockwell doc #RI/RD91-136. Monitoring & Effluent Annual Report 1990. Report of site emissions and local area samples, near both DeSoto and SSFL sites. Incl report of non-rad emissions. Incl self-assmt for JAN- MAR91.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001682	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1991	1/1/1991		13, 10	94 pg. Rockwell doc #RI/RD92-138. ASER 1991. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001683	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1992	1/1/1992	Radiation Protection and Health Physics Services	13, 10	118 pg. Rockwell doc #RI/RD93-125. ASER 1992, Rev A (DEC93). Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001684	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1993	1/1/1993	Radiation Protection and Health Physics Service and Environmental Protect	13, 10 tion	118 pg. Rockwell doc #RI/RD94-126. ASER 1993. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001685	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1994	1/1/1994	Radiation Protection and Health Physics Services and Environmental Protection	13, 10	118 pg. Rockwell doc #RI/RD95-153. ASER 1994. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001686	Rocketdyne Division Annual Site Environmental Report SSFL and DeSoto Sites 1992	1/1/1985	Staff of Environmental Remediation	I 13, 10	116 pg. Rockwell doc #RI/RD96-140. ASER 1995. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001687	Rocketdyne Propulsion and Power DOE Operations Annual Site Environmental Report 19		R. J. Tuttle	13, 10	138 pg. Rockwell doc #RD97-134. ASER 1996. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001688	Rocketdyne Propulsion and Power DOE Operations Annual Site Environmental Report 19		K. S. Robinson	13, 10	114 pg. Rockwell doc #A4CM-ZR-0012. ASER 1997. Report of site emissions and local area samples, near both DeSoto and SSFL sites, both rad and non-rad.
ET001690	Environmental Monitoring Report SSFL Vol 3 Jjune 1991	6/1/1991	Rockwell Internation	10	300 pg. JUN91 SSFL Quarterly Envir Monitoring Report, Vol 3 Groundwater Treatment & Monitoring. JAN-MAR91, RD ltr 91RC07065 Atts 1—4 Wells & analyses (not incl Qtly GW report, #8640M-137)
ET001691	Environmental Monitoring Report SSFL Vol 3 Ju 1992	ne 6/1/1992		10	370 pg. JUN92 SSFL Quarterly Envir Monitoring Report, Vol 3 Groundwater Treatment & Monitoring. JAN-MAR92, RD ltr 92RC05658 Atts 1—3 Wells & analyses (not incl Qtly GW report, #8640M-171)
ET001692	Environmental Monitoring Report SSFL Voolume Ground Water Treatment and Monitoring	9/1/1992	Rockwell International	10	102 pg. SEP92 SSFL Quarterly Envir Monitoring Report, Vol 3 Groundwater Treatment & Monitoring. APR-JUN92, RD Itr 92RC08521, Regulatory Affairs correspondence (does not incl Qtly GW report, #8640M-179)

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET001693	Environmental Monitoring Report SSFL Vol 3 December 1992	12/1/1993	Rockwell International	10	124 pg. DEC92 SSFL Quarterly Report, Vol 3 GW Treatment & Monitoring. NOV92: JUL-SEP92, RD ltr 92RC12000, Qtly GW Monitoring Report, #8640M-184.
ET002002	DOE Letter to Rockwell International Re: Hazardous Waste and radioactive Mixed Waste Management Plan	4/16/1984	James T. Davis; DOE	7	2 pg. DOE Letter to Rockwell/ESG DOE Comments on Rockwell's Hazardous Waste and radioactive Mixed Waste Management Plan
ET002010	Rockwell Letter to DOE re: SAN Appraisal of Nuclear Facility Safety at RMDF	9/21/1984	M.E. Remley, Rockwel	II 7	5 pg. Ltr 84ESG-3902 from RI-ESG to DOE-SAN/ESO. Response to 4 recommendations for improvement, from SAN's MAY84 assessment of RMDS nuclear facility and criticality safety.
ET002013	DOE Letter to Rocketdyne Re: ESG Environment & Affluent Monitoring Program Apprasal , Conducted December 19-21, 1983	al 2/6/1985	Michael E. Long; DOE	7	5 pgs. Ltr from DOE-SAN/ESO. Acceptance of corrective actions on DEC83 appraisal. Appraisal closed.
ET002014	DOE Letter to Rocketdyne Re: Nuclear Facility Safety & Criticality Appraisal of the RMDF, Conducted May 22-23, 1984	2/15/1985	Michael E. Long; DOE	7	6 pgs. Ltr from DOE-SAN/ESO. Acceptance of corrective actions on MAY84 appraisal. Appraisal closed.

٤.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002015	DOE Letter to Rocketdyne Re: SAN Appraisal of ESG/ETEC Radiography & Sealed Source Program, conducted February 27-29, 1984	6/20/1984	Terry A. Vaeth, DOE	7	11 pgs. Ltr from DOE-SAN/ESO. Acceptance of corrective actions on FEB84 appraisal. Appraisal closed.
ET002019	Rockwell letter to DOE Re: Review of Nuclear Facility Operational Safety Requirements	3/9/1987	M.E. Remley; Rocketdyne	7	2 pgs. Ltr 87RC02771 Rocketdyne to DOE-SAN/ESQA. Response to DOE's FEB87 review of RMDF nuclear facility safety
ET002020	Rockwell Letter to DOE Re: Environmental Monitoring Annual Report-1986	3/26/1987	M.E. Remley; Rocketdyne	7, 10	1 pg (w/o att). Ltr 87RC03343 from Rocketdyne to DOE-SAN/ESQA. Xmtl of 1986 Environmental Monitoring Annual Report
ET002023	Rockwell Letter to DOE Re: EPS's Consideration to Eliminate RCRA Exclusions for a 90-day Hazardous Waste Storage Tanks and Containers		M.E. Remley; Rocketdyne	15	5 pg. Ltr 86RC12629 Rocketdyne to DOE-SAN/ESQA questionaire summarizing waste storage tanks.

<b>DIIN</b> ET002027	Title Synopsis of SSFL Work Group Dec 14 Meeting	<b>Date Created</b> 12/14/1989	Author Jim Hartman	Responds to question #	Synopsis 3 pgs.
ET002051	DOE Letter to Rocketdyne Re: Rocketdyne Radiation Exposures for 1984	5/15/1985	Michael E. Long	7	1 pg. DOE-SAN/ETEC ltr summarizing DOE's review of Rocketdyne's Annual Rad Exposure Report
ET002052	DOE Memo Re: Rocketdyne Radiation Exposures for 1984	s 4/22/1985	James T. Davis; DOE	7	1 pg. DOE-SAN/ESQA memo summarizing DOE's review of Rocketdyne's Annual Rad Exposure Report
ET002203	Safety Analysis for Building 1020 Operations TRUMP-S	12/4/1989	J Guon; Rockwell International	20	10 pgs. Rocketdyne doc #190ER000011. Safety Analysis for Building T020 (RI Hot Lab) TRUMP-S operations.
ET002204	Revised TRUMP-S Project Radioactive Materials Usage Application	10/31/1989	J. Guon and L. Grantham; Rockwell International	20	52 pgs. Rocketdyne doc #190Tl000001. Revised TRUMP-S Project Radioactive Materials Usage Application

s. •

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002207	TRUMP-S Test Program- Nuclear Materials Management Plan	10/17/1989	V.J. Schaubert	17	38 pgs. Rocketdyne doc #190NMP000001. TRUMP-S Test Program- Nuclear Materials Management Plan
ET002208	Briefing Paper: TRUMP Program at SSFL	10/19/1989		7	2 pgs. Briefing Paper: TRUMP Program at SSFL (B020 RI Hot Lab)
ET002209	Test Readiness Review: TRUMP-S Hot Glove B Test	ox10/13/1989		7	9 pgs. Briefing package. Readiness Review: TRUMP-S Hot Glove Box Test
ET002211	Letter to R.M. Mucica, Rockwell International Corporation Re: Contract DE-AC03-87SF16893 COTR Program Guidance	10/2/1989	Ken Quitoriano	7	1 pg. Draft ltr to R.M. Mucica, Rockwell International Re: Contract DE-AC03-87SF16893 COTR Program Guidance to halt TRUMPS tests in RI Hot Lab pending NEPA determination.
ET002212	Rockwell Hot Cell NRC License Renewal- Public Hearing	9/29/1989	Ken Quitoriano	7	1 pg. Briefing paper. Rockwell Hot Cell NRC License Renewal- Public Hearing

4 1

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002213	Environmental Assessment of Operations at Energy Systems Group of Rockwell International under Special Nuclear Materials License SNM-21	8/25/1982	Rockwell International	7	32 pgs. Rockwell doc #ESG-82-32. Environmental Assessment of Operations under Special Nuclear Materials License SNM-21. 1982 Supplement to Al-76-21
ET002214	Contract Summary Report, Project Status Report, Cost Performance Report for August 1989	, 9/19/1989	J.E. Gackle	7	8 pgs. AUG89 Contract Summary Report, Project Status Report, Cost Performance Report, 87SF16893
ET002216	Contract Summary Report, Project Status Report, Cost Performance Report for October 1989	. 11/22/1989	J.E. Gackle; Rockwell International	7	8 pgs. OCT89 Contract Summary Report, Project Status Report, Cost Performance Report, 87SF16893
ET002222	Review of SSFL Radiological Environmental Monitoring Program	5/1/1990	Dr. Daniel Montgomery	, 3	32 pgs. (title page missing) Rocketdyne's Review of SSFL Radiological Environmental Monitoring Program, APR-MAY90. Radiation
ET002224	Environmental Impact Assessment of Operations Atomics International Under Special Nuclear Materials License No. SNM-21	at10/18/1977	7 Rockwell International	7, 21	400 pgs. Rockwell #AI-76-21. Environmental Impact Assessment of Operations at Atomics International Under Special Nuclear Materials License No. SNM-21

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002227	Notes Re: Rockwell will not pursue license renew of Hot Cell	al		7, 21	1 pg. Handwritten briefing: ~05APR90. Rockwell will not pursue license renewal of Hot Cell. The TRUMP-S work will be relocated to University of Missouri.
ET002239	DOE Memorandum re: Nonradioactive Transuranic Management by Pyroproccessing- Separation (TRUMP-S) Experiments at Santa Susana Field Laboratory	9/18/1990	. William H. Young	7	2 pgs. Memo from DOE-HQ/NE-1:3 pgs. Action Description Memo for TRUMP-S Experiments at SSFL (no effect). Final approval.
ET002240	Nuclear Operations at Rockwell's Santa Susana Field Laboratory- A factual Perspective	10/2/1990	R.D. Oldenkamp; Rockwell International	7	65 pgs. Rockwell #N001ER000017. Report: Nuclear Operations at Rockwell's Santa Susana Field Laboratory- A factual Perspective

•

<b>DIIN</b> ET002502	Title San Radiation Safety Appraisal at the Energy Systems Group	<b>Date Created</b> 4/22/1980	Author Rockwell International	Responds to question #	Synopsis 15 pg. Report.
ET002507	Response to Review of Radiation Safety at ESG	12/21/1982	Rockwell International	7, 8	2 pg: from RI/ESG: proposed Response to Review of Radiation Safety at ESG
ET002508	Radiographer Training and Qualification form/NRC License criticality control	9/3/1982	Rockwell International	7, 8	5 pgs. Ltr from RI/ESG: historical Worker radiation exposure level. (att does not match letter subject).
ET002509	The Hallam Cask Incident	2/8/1984	Rockwell International	3, 7, 8	4 pgs. Interim report on leaky rad waste shipping cask.
ET002510	Environmental Assessments	1/31/1984	Rockwell International	3, 10	5 pgs. Ltr from RI/ESG: Identification of potential environmental problems at ETEC/SSFL.

2 b

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002511	Leaking of Radioactive Material Shipping Cask	1/30/1984	Rockwell International	3, 7, 8	1 pg. Note: initial report of Leaking from empty Radioactive Material Shipping Cask
ET002513	Report of Review of Radiation Safety at ESG	9/23/1982	Rockwell International	7, 8	6 pgs. Ltr from DOE-SAN/ESS: Report of Review of Radiation Safety at ESG
ET002514	San Appraisal of ESG Radiographic safety and Criticality Safety Programs	6/2/1982	Rockwell	7, 8	1 pgs. Ltr from DOE-SAN/ESS: confirm dates for Review of Radiation Safety at ESG
ET002524	Radiological Safety Incident Report	5/28/1981	Rockwell International	3, 7, 8	2 pgs. Rad Safety Incident Report: T022: Spent fuel cask with failed fuel element spilled liquid on floor. Decon'd and returned to work. Radiation.
ET002525	Request for Radioactive Material and Radiation- Producing Device User Authorization for RMDF Operation	12/20/1982	Rockwell International	8	5 pgs, letter

DIIN		Date reated Author	Responds to question #	Synopsis
ET002542	Radiological Safety Incident Report (Building 064) ®9/2	21/1982 Rockwell Internationa	1 7,8	1 pg. Radiation Incident Report: B064: spurious RAS alarm. Returned to work.
ET002543	Radiological Safety Incident Report (T028 Hold-up 1/20 Pond) ®	0/1982 Rockwell Internationa	1 7,8	1 pg. Radiation Incident Report: T028 Pond: Stuck closed Low-level float switch caused false alarm. Referred to Maintenance.
ET002544	Radiological Safety Incident Report (Building 064) 1/12	2/1982 Rockwell Internationa	1 7, 8	1 pg. Radiation Incident Report: B064: spurious RAS alarm. Returned to work.
ET002545	Radiological Safety Incident Report (ETEC T356) ®12/	/8/1981 Rockwell Internationa	1 7,8	7 pg. Radiation Incident Report: T356: Radiography source failed, and fell to floor. Personel evacuated. No overexposures. Returned to work.
ET002546	Radiological Safety Incident Report (RMDF T021) 12/4	/4/1981 Rockwell Internationa	I 3, 7, 8	2 pg. Radiation Incident Report: RMDF T021: Excess rad liquid found in fuel cask. Flagged for repackaging. No exposures.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002548	Radiological Safety Incident Report (RMDF T022 ®	2)11/24/1981	Rockwell International	3, 7, 8	1 pg. Radiation Incident Report: RMDF T022: storage buckets found unsealed. Buckets were closed. No release.
ET002553	Radiography and Sealed Source Program	2/27/1983	DOE	7, 8	3 pgs. Notice of planned FEB84 appraisal of ETEC Radiography & sealed source program.
ET002557	Updated FY 1992 Site Specific Plan for the Environmental Remediation and Waste Management Five-Year Plan	3/6/1990	Rockwell International	20	36 pgs. Ltr from RI/ETEC: Updated FY 1992 Site Specific Plan for the ERWM Five-Year Plan
ET002562	Revised FY 1992 Activity Data Sheets for the Environmental Restoration and Waste Management Five-Year Plan	6/20/1990	Rockwell International	7, 20	2 pgs (w/o att). Itr from RI/ETEC: xmtl of Revised FY92 Activity Data Sheets for the ERWM Five-Year Plan

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002573	B/028 & B/374 Progress Report as of November 17, 1988	11/23/1988	Rockwell International	16	3 pg. Ltr from RI/ETEC
ET002574	B/028 & B/374 Progress Report for July 1988	8/10/1988	Rockwell International	16	3 pg. Ltr from RI/ETEC
ET002596	Contract Management Summary Report, February1988 for Contract DE-AC03-81SF11565	3/3/1988	Rockwell International W.F. Dennison	, 16	2 pgs. Ltr from RI/Canoga Park: FEB88 Contract Management Summary report on B055/NMDF
ET002602	Monthly Progress Report, December 1987, Contract DE-AC03-81SF11565	1/5/1988	Rockwell International W.F. Dennison	, 16	3 pgs. Ltr from RI/Canoga Park: DEC87 Progress report on B055/NMDF
ET002603	Monthly Progress Report, November 1987 Contract DE-AC03-81SF11565	12/4/1987	Rockwell International L.G. Kellogg	, 16	3 pgs. Ltr from RI/Canoga Park: NOV87 Progress report on B055/NMDF

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002604	Contract Management Summary Report, November 1987 for Contract DE-AC03-81SF1156	12/3/1987 5	Rockwell International L.G. Kellogg	, 16	2 pgs. Ltr from RI/Canoga Park: NOV87 Contract Management Summary report on B055/NMDF
ET002606	Monthly Progress Report, October 1987 Contract DE-AC03-81SF11565	11/6/1987	Rockwell International L.G. Kellogg	, 16	3 pgs. Ltr from RI/Canoga Park: OCT87 Progress report on B055/NMDF
ET002611	Monthly Progress Report, September 1987 Contract DE-AC03-81SF11565	10/7/1987	Rockwell International L.G. Kellogg	, 16	3 pgs. Ltr from RI/Canoga Park: SEP87 Progress report on B055/NMDF
ET002614	Sodium and Lithium Disposal at Energy Technology Engineering Center	1/30/1989	DOE, Anthony J. Adduci	7	1 pg. ltr from DOE-SAN/NED. Direction to Continue operation at burn pit per old permit.
ET002620	Monthly Progress Report, August 1989, Contract De-AC03-81SF11565	9/15/1989	Rockwell International T.A. Moss	, 16	3 pgs. Ltr from RI/Canoga Park: AUG89 Progress report on B055/NMDF

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002624	Monthly Progress Report July 1989 Contract DE- AC03-81SF11565	8/15/1989	Rockwell International, T. A. Moss	16	3 pgs. Ltr from RI/Canoga Park: JUL89 Progress report on B055/NMDF
ET002627	Monthly Progress Report, June 1989 Contract DE AC03-81SF11565	- 7/10/1989	Rockwell International, T.A. Moss	. 16	4 pgs. Ltr from RI/Canoga Park: JUN89 Progress report on B055/NMDF
ET002632	Monthly Progress Report, May 1989 Contract DE-AC03-81SF11565	6/8/1989	Rockwell International, T.A. Moss	. 16	4 pgs. Ltr from RI/Canoga Park: MAY89 Progress report on B055/NMDF
ET002633	Monthly Progress Report, April 1989 Contract DE-AC03-81SF11565	- 5/15/1989	Rockwell International, T.A. Moss	. 16	3 pgs. Ltr from RI/Canoga Park: APR89 Progress report on B055/NMDF
ET002636	Monthly Progress Report, March 1989 Contract De-AC03-81SF11565	4/10/1989	Rockwell International, T.A. Moss	. 16	3 pgs. Ltr from RI/Canoga Park: MAR89 Progress report on B055/NMDF

.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002639	Monthly Progress Report, Frebruary 1989 Contract DE-AC03-81SF11565	3/31/1989	Rockwell International, T.A. Moss	16	3 pgs. Ltr from RI/Canoga Park: FEB89 Progress report on B055/NMDF
ET002642	Monthlly Progress Report, January 1989 Contract De-AC023-81SF11565	2/8/1989	Rockwell International, T.A. Moss	16	3 pgs. Ltr from RI/Canoga Park: JAN89 Progress report on B055/NMDF
ET002645	Monthly Progress Report, December 1988 Contract DE-AC03-81SF11565	1/6/1989	Rockwell International, W.F. Dennison	16	3 pgs. Ltr from RI/Canoga Park: DEC88 Progress report on B055/NMDF
ET002648	Monthly Progress Report November 1988 Contrac De-AC03-81SF11565	112/9/1988	Rockwell International, W.F. Dennison	16	3 pgs. Ltr from RI/Canoga Park: NOV88 Progress report on B055/NMDF
ET002651	Monthly Progress Report, October 1988 Contractact De-AC03-81SF11565	11/7/1988	Rockwell International, W.F. Dennison	16	4 pgs. Ltr from RI/Canoga Park: OCT88 Progress report on B055/NMDF

	DIIN	Title	Date Created	Author	Responds to question #	Synopsis
·	ET002653	Monthly Progress Report, September 1988 Contract DE-AC03-81SF11565	10/6/1988	Rockwell International, W.F. Dennison	16	3 pgs. Ltr from RI/Canoga Park: SEP88 Progress report on B055/NMDF
	ET002654	Monthly Progress Report, August 1988 Contract DE-AC03-81SF11565	9/2/1988	Rockwell International, W.F. Dennison	16	4 pgs. Ltr from RI/Canoga Park: AUG88 Progress report on B055/NMDF
	ET002656	Monthly Progress Report, July 1988 Contract DE-AC03-81SF11565	8/4/1988	Rockwell International, W.F. Dennison	16	3 pgs. Ltr from RI/Canoga Park: JUL88 Progress report on B055/NMDF
	ET002659	Review of Volatile Organics in Groundwater at T059, SSFL	2/17/1987	Rockwell International, R.J. Tuttle	3, 10	3 pgs. Ltr from RI/Tuttle: Groundwater samples around T059 found no Cobalt- 60, but found high tetrachloroethene (perc; ~40 ppb)
	ET002660	Cover letter for Groundwater Investigation Monthly Progress Report	/ 1/14/1987	Rockwell International, R.W. Buckles	10	2 pg xmtl. Ltr from Rockwell to RWQCB. Cover on Groundwater Investigation Monthly Progress Report

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002661	Rocketdyne/SSFL Groundwater Investigation Monthly Report	1/12/1987	Groundwater Resources Consultants, Inc., Davi B. Hawkins	10 d	30 pg report. SSFL Groundwater Investigation Monthly Progress Report, DEC86.
ET002662	SSFL Groundwater Program Bimonthly Report	10/8/1987	Rockwell International, J.A. Bowman	10	3 pg xmtl (w/o att) Ltr from Rockwell to RWQCB. Cover on SSFL SSFL Groundwater Investigation bi-monthly Progress Report
ET002663	Santa Susana Field Labroatory Bimonthly Report	9/21/1987	Groundwater Resources Consultants, Inc., Gen- Foushee, Chuck Dickens	10	4 pgs report. SSFL Groundwater Investigation bi-Monthly Progress Report, AUG87.
ET002664	SSFL Groundwater Program Bimonthly Report	1/13/1987	Rockwell International, J.A. Bowman	. 10	4 pg xmtl (w/o att) Ltr from Rockwell to RWQCB. Cover on SSFL SSFL Groundwater Investigation bi-monthly Progress Report
ET002665	Rocketdyne/SSFL Groundwater Investigation Monthly Report	8/5/1987	Groundwater Resources Consultants, Inc., Dinah Jasensky	10	30 pg report. SSFL Groundwater Investigation Monthly Progress Report, JUN87.

•

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002666	Phase I and Phase II plans to investigate and characterize the SSFL	5/23/1984	Rockwell International, W. J. Costas	10	16 pgs. Ltr from Rockwell and summary plans for Phase I and Phase II investigate and characterize the SSFL groundwater, responding to RWQCB discovering trichloroehylene (TCE)
ET002667	Decontamination Plan for Atomics Internaitonal Facilities Licensed Under Special Nuclear Material License SNM-21	3/10/1978	Rockwell International, Health Safety, and Radiation Services Department	7, 16	Decontamination Plan for Atomics Internaitonal Facilities covered by NRC Special Nuclear Material License SNM- 21 (incl SSFL B4020, B4055, and B-172)
ET002671	Environmental Impact Appraisal for Renewal of Special Nuclear Material License No. SNM-21	6/1/1984	U.S. Nuclear Regulatory Commission	21, 7	120 pgs. NRC: Environmental Impact Appraisal for Renewal of Al Facilities' Special Nuclear Material License No. SNM-21, Docket # 70-25. Only B020/Hot Lab effective. Incl 1980 Effluent Monitoring Report. Radiation.
ET002672	ESG Environmental and Effluent Monitoring Program Appraisal, December 19-21, 1983	1/23/1985	Rockwell International, M.E. Remley	3, 7	3 pgs. Ltr from Rocketdyne. Final corrective actions on DEC83 appraisal.
ET002673	ESG Environmental and Affluent Monitoring Program Appraisal, Conducted December 19-21, 1983	2/6/1985	DOE, Michael Long, ETEC Office Director	3, 7	5 pgs. Ltr from DOE-SAN/ESO. Acceptance of corrective actions on DEC83 appraisal. Appraisal closed.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002678	ESG Environmental and Effluent Monitoring Program Appraisal, December 19-21, 1983	4/5/1984	DOE, Terry Vaeth, ETEC Site Office Director	3, 7	6 pgs. Ltr from DOE-SAN/ESO. Results of DEC93 appraisal. 5 Recommendations.
ET002679	Environmental Monitoring Appraisal Notes - handwritten (DOE 5484.1 order - radiation)	12/19/1983	DOE	7, 8	1 pg. Audit Team Note outlining the intended audit and initial findings.
ET002680	ESG Environmental and Effluent Monitoring Program Appraisal, December 19-21, 1983	4/27/1984	Rockwell International, M.E. Remley	7	1 pg. Ltr from Rockwell-ESG. Require more time to form 5 Corrective actions on DEC83 appraisal.
ET002681	Environmental Monitoring Appraisal Findings - (handwritten notes)	12/21/1983	EOE	7, 8	1 pg. Audit Team Note outlining the audit results and proposed findings.
ET002683	Building 059 Pipe Chase Room Remediation Project Readiness Review	5/1/1988	Rockwell International	7, 16	80 pgs. Briefing materials for Building 059 LLTR Pipe Chase Room Remediation Project

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002689	Routine Effluent Monitoring Report to NRC	8/1/1989	Rockwell International, R. J. Tuttle	3, 10, 13	1 pg (w/o att). Ltr from RI-Rocketdyne: Copy of routine effluent Monitoring Report to NRC (on AI non-ETEC activities)
ET002690	Effluent Monitoring Report	7/17/1989	Rockwell International, R.J. Tuttle	3, 10, 13	3 pgs. Ltr from RI-Rocketdyne: Routine effluent Monitoring Report to NRC on SNM-21 (Al non-ETEC activities). Radiation
ET002692	Update of RMDF Part A Permit Application, EPA ID # CA3890090001	12/11/1989	Rockwell International, S.R. Lafflam	7	8 pgs. Ltr from RI-Rocketdyne: Copy of Update to RMDF Part A Permit Application, EPA ID # CA3890090001
ET002694	Report of Violation and Schedule for Compliance, Rockwell International Corporation, Rocketdyne Division, Santa Susana Field Laboratory	10/5/1989	Rockwell International, S.R. Lafflam	7	10 pgs. Ltr from RI-Rocketdyne: Rocketdyne response to Citations from AUG89 inspection, Report of Violation and Schedule for Compliance, Rocketdyne/SSFL. Cites numerous typos and factual inaccuracies. Counts were all across SSFL, incl land near T4059.
ET002695	Metal and Radiological Sampling Processes (faxed document)	9/20/1989		7, 8	4 pgs. Summary procedures for environmental sampling at ETEC. 5 samples along north fence. Request for comments.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002696	Resubmittal of Solid Waste Management Unit Information for Rockwell International Corporation Rocketdyne Division, Santa Susana Field Laboratory (SSFL)	9/20/1989	Rockwell International, S. R. Lafflam	3	1 pg (w/o att). xmtl Ltr 89RC11360 from RI-Rocketdyne to Cal-DTSC. Supplemental submitttal of missing pages relating to 15SEP's SWMU package.
ET002697	Closure Report, Santa Susana Field Laboratory, Surface Impoundments (CAD 093365435 and CA 1800090010)		Rockwell International S.R. Lafflam	3, 7	1 pg (w/o att). xmtl Ltr 89RC11355 from RI-Rocketdyne to Cal-DTSC. Closure Report, SSFL, Surface Impoundments (CAD 093365435 and CA 1800090010)
ET002698	Solid Waste Management Unit Submittal for Rockwell Internation Corporation, Rocketdyne Division, Santa Susana Field Laboratory	9/14/1989	Rockwell International	3, 7	1 pg (w/o att; 2nd pg missing). xmtl Ltr 89RC11351 from RI-Rocketdyne to Cal- DTSC. Information on Solid Waste Management Units for SSFL (incl CA38900900001 at ETEC)
ET002702	Notes of Meetings with Regulators regarding permits	4/27/1990	DOE, Gary Lavagnino	9	2 pgs. Notes by DOE-SAN/Lavagnino of April Meetings with Regulators regarding permits
ET002703	Notes on Meetings with Regulators on permits - Bldg. 059	2/2/1990	DOE, Gary Lavagnino	16	1 pgs. Notes by DOE-SAN/Lavagnino: Analysis of AUG89 Report of Violation (ROV) against Rocketdyne and SSFL. Back and forth comments between DHS/DTSC and Rocketdyne. As of 10/05/89, one count applicable to ETEC (T059 waste handling) remains active.

. . .

	DIIN	Title	Date Created	Author	Responds to question #	Synopsis
	ET002704	Notes on inspection and meetings with the Department of Health Services - Bldgs. 029, 133	1/31/1990	DOE, Gary Lavagnino	17	1 pg. Notes by DOE-SAN/Lavagnino of JAN90 Cal-DHS inspection of Area IV and ETEC facilities. Focus on Permitted facilities and large generators. Minor issues noted, plus a lingering concern about stranded Sodium waste drum at B029.
·	ET002706	Dollars for Drilling and Sampling Off-site Monitoring Wells	1/30/1990	DOE SF, Anthony J. Adduci	10	2 pgs. Ltr from DOE-SAN/ESO. Summary of discussion about Dollars for Drilling and Sampling Off-site Monitoring Wells
	ET002711	Status of Environmental Compliance Activities at the Santa Susana Field Laboratory, CA	7/25/1989	DOE, John E. Baublitz	7	7 pgs. Memo from DOE/NE-23. Status of Environmental Compliance Activities at the Santa Susana Field Laboratory, CA
	ET002719	Rocketdyne/SSFL Phase II Monthly Report	7/14/1986	Rockwell International, R. W. Buckles	10	3 pg (w/o att). Xmtl Ltr 86RC09007 from Rockwell to RWQCB. Cover on Rocketdyne/SSFL Phase II Groundwater Investigation Monthly Progress Report
	ET002720	Storm Water Discharge Permits	7/7/1986	DOE, James T. Davis	10	3 pgs.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002721	Groundwater Investigation (DOE Briefing)	6/25/1986	Rockwell International	10	34 pg groundwater investigation briefing package
ET002723	Status Report for the Rockwell Internation corportporation, Rocketdayne Division, Santa Susana Field laboratory Groundwater Investigation the 4/15/86-5/3/86	5/15/1986 on	Rockwell International R. W. Buckles	. 10	2 pgs. Ltr 86RC05974 from Rocketdyne to RWQCB.
ET002725	Submittal of Building T/029 Decontamination Report	7/24/1990	Rockwell International S.R. Lafflam	, 16, 7	1 pg (no att). xmtl ltr 90RC09157
ET002728	DOE D&D of Property at Santa Susana Field Laboratory	7/10/1989	DOE SAN, James k. Hartman	7	1 pg. Ltr from DOE-ERWM. DOE intent to remediate radioactive contamination at B009, B005, and Old Burn Pit (all outside of ETEC). Radiation.

€ < 1 •

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002729	SSFL Site Radiological Survey	2/18/1988	Rockwell International, K. T. Stafford	, 3	1 pg (w/o att). Ltr 88ETEC-DRF-0419 from RI-ETEC. Radiological survey results from B005.
ET002733	ESG Environmental and Effluent Monitoring Program Appraisal, December 19-21, 1983	4/5/1984	DOE, ETEC Site Office Director, Terry Vaeth	9 3, 10, 13	6 pgs. Ltr from DOE-SAN/ESO. Results from ESG Environmental and Effluent Monitoring Program Appraisal, December 19-21, 1983. 5 Recommendations.
ET002734	Environmental Monitoring Annual Report - 1987	3/28/1988	Rockwell International M.E. Remley	, 3, 10, 13	1 pg (w/o att). Ltr 88RC-03446 from Rocketdyne to DOE-SAN/ESO.
ET002737	Letter to NUS Corporation Re: Environmental Survey at Santa Susana Field Laboratories	3/10/1988	M.E. Remley, Rockwel International	II 7, 8	
ET002739	Environmental Monitoring Annual Report - 1987	3/28/1998	Rockwell International M.E. Remley	, 3, 10, 13	1 pg (w/o att). Ltr 88RC-03437 from Rocketdyne to DOE-SAN/ESO.

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002740	Changes for the 1988 Annual Environmental Repo	ort4/15/1983	DOE, James T. Davis	3, 10, 13	4 pgs.
ET002741	Environmental Assessments	1/31/1984	Rockwell International, R.O. Williams, Jr.	, 3, 10, 13	5 pgs. Ltr 84ESG-250 from RI-ESG to DOE-SAN/MO: results of ETEC self-assessment of potentially problematic facilities.
ET002742	Environmental Audits	1/11/1984	DOE, James T. Davis	3, 10, 13	5 pgs. Ltr from DOE-SAN/ESQA: ETEC should perform self-assessment of potentially problematic facilities.
ET002745	Facility Stack Monitoring at Rocketdyne	5/29/1985	Rockwell International, Me. E. Remley	, 13	4 pgs. Rocketdyne's Facility Stack Monitoring procedures (mixed ETEC and NRC-facilities)
ET002747	Environmental Monitoring Annaul Report - 1984	4/11/1985	Rockwell International, M. E. Remley	, 3, 10, 13	5 pgs. xmtl ltr 85RC05219 from Rocketdyne to DOE-SAN/ESO. Replacement pages for 1984 Environmental Monitoring Annaul Report, previously transmitted 01APR85 under 85RC04608

e the

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002748	ESG Environmental & Affluent Monitoring Program Appraisal, Conducted December 19-21, 1983	m 2/6/1985	DOE, ETEC Site Office, Michael E. Long	3, 10, 13 g	5 pgs. Ltr from DOE-SAN/ESO. Acceptance of corrective actions on DEC83 appraisal. Appraisal closed.
ET002765	Shipment of Waste to Envirocare under U.S. Arm Corps of Engineers Kansas City District Contract DACW41-93-D-9001	y 9/5/1995	DOE, Deputy Division Director, Daniel Nakahara	<sup>1</sup> 17	Letter Pkg. 4 pgs. From DOE-OAK/WMD: approval for Shipment of 400yd³ LLW soils to Envirocare under Contract DACW41-93-D-9001. radiation
ET002766	Disposal of ETEC Low Level Radioactive Waste a Envirocare	at 6/5/1995	DOE, Deputy Director, Daniel N. Nakahara	, 17	Letter. 1 pg. From DOE-OAK/WMD: Request to ship 400yd³ LLW soils to Envirocare under DOE-COE Interagency agreement.
ET002768	ETEC Annual Waste Management Plan	12/28/1994	DOE, Group Leader, Daniel N. Nakahara	17	Letter. 1 pg. From DOE-OAK/WMD: DOE approves ETEC Annual Waste Management Plan

DIIN	Title	Date Created	Author	Responds to question #	Synopsis
ET002774	Validation of Rocketdyne Transuranic Waste Dat	a 4/19/1994	DOE, Operations Program Manager, Roy Kearns	17, 7	Letter. 3 pgs. From DOE-OAK/WMD: Assent on Rocketdyne Hot Lab B020 Transuranic Waste drum characterization Data
ET002780	ETEC's December 21, 1990 Quarterly Environmental Status Report - October through December 1990	3/6/1991	DOE, Joseph P. Juetten, Director Environment and Safe Support Division	7 ty	Letter. 2 pgs). From DOE-SAN/ESS: Local review of ETEC's December 1990 Quarterly Environmental Status Report
ET002783	Conditional Resumption of Treatment Operations at Building 133	4/19/1996	DOE, Phillip E. Hill, Director, Waste Management Division	7	Letter. 2 pgs. From DOE-OAK/WMD: Approve Conditional Resumption of Treatment Operations at Building 133
ET33XX004558	Letter to R.J. Tuttle Re: Off-scale Reading Personal Dosimeter	2/19/1982	J.W. Breese, Rockwel International	3, 7, 8	
ET33XX004559	Letter to Radiation & Nuclear Safety Group Re: Radiological Safety Incident Report	1/25/1982	R.J. Tuttle, Rockwell International	3, 7, 8	